


SR 562 Hood TH3

Spare parts / Accessories



No.	Description	Ordering No.
1.	O-ring for hose	R06-0202
2.	Hood	R06-5101
3.	Head harness	R06-5002
4.	Sweat band	R06-0504
5.	Hose	R06-5003
6.	Adapter for hose	T06-5001
	SR 5226 Cleaning wipes. Box of 50.	H09-0401